



## Ft. Lauderdale, FL Apartment Case Study Results

### Notes:

- Fresh Air being piped into units
  - Outdoor RH Range: 70% - 95%
- Indoor Relative Humidity Results
  - Prior to IW25-1 Installation: 67 – 78% RH
  - After IW25-1 Installation: 52 – 56% RH

